

## Identifying Shift Sensor Type

The IWP Shift Sensor F300-F0055-0000 has been discontinued and replaced with an updated sensor, F300-A0241-0000. For some applications this will require replacing the cable that connects the sensor to the waterjet pump. This document will help identify the correct parts for your application.

**New Connector Style:** If you have the screw together type (M12) three pin connector, the IWP Shift Sensor F300-A0241-0000 is a direct fit.



**Old Connector Style:** If you have the push together rubber 2 pin connector, you will need the IWP Sensor Update Kit F300-K0195-0000.

